



#### Reliable

Maximum measurement reliability

#### Cost effective

Long-term availability of the measuring sensor

#### User friendly

Maintenance-free, thanks to self-cleaning effect of the flush-mounted diaphragm

## Dewatering wells in open cast mining

### Level measurement in groundwater control in dewatering wells

In open cast mining, the groundwater levels must be continuously reduced to protect the mining area from flooding and the excavation walls from instability due to water pressure. A large number of dewatering wells with submersible pumps are kept in operation for this purpose. A continuous water flow prevents the pump shaft from blocking due to the effects of hardening clay/iron oxide deposits. To regulate the pump output, precise level measurement is required in each of the up to 750 m deep wells.

[More details](#)



#### VEGAWELL 52

Level measurement via submersible pressure transmitter for regulation of pump Output

- Reliable, maintenance-free measurement
- Measurement reduces pump operating costs through output control
- Abrasion resistant CERTEC® ceramic measuring cell

[Show Product](#)

PRO

**VEGAWELL 52**

[Show Product](#)



**Measuring range - Pressure**

0 ... 60 bar

**Process temperature**

-20 ... 80 °C

**Process pressure**

-

**Accuracy**

0.1 %

**Materials, wetted parts**

PVDF  
316L  
Duplex (1.4462)  
FEP  
PE  
1.4301  
Titanium

**Seal material**

EPDM  
FKM  
FFKM

**Protection rating**

IP66/IP67  
IP68

**Output**

4 ... 20 mA  
Two-wire: 4 ... 20 mA/HART

**Ambient temperature**

-40 ... 80 °C